Oil Field Environmental Incident Summary

Responsible Party: Petro Harvester Operating Company, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: EARL 1

Field Name: PORTAL Well File #: 10902

Date Incident:2/27/2015Time Incident:14:30Facility ID Number:County:BURKETwp:164Rng:91Sec:31Qtr:

Location Description:

Submitted By: Gary Watson Received By:

Contact Person: Galen Kalmbach

103 First Avenue NE Mohall, ND 58761

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:0.8 MileDistance Nearest Water Well:0.8 Mile

Type of Incident Valve/Piping Connection Leak

Release Contained in Dike No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 5 Barrels 5 Barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Minimal effect on cultivated land.

Areal Extent:

5 bbl of oil pool outside of dike - 20' x 20'. A fine oil mist deposited on the snow - 30' x 75'.

Tuesday, March 24, 2015 Page 1 of 2

Potential Environmental Impacts:

Minimal effect on cultivated land.

Action Taken or Planned:

Jim Potts - NDIC inspector was notified. The landowner and tenant farmer will be identified and notified as soon as possible. The affected snow cover and soil will be scraped-up, collected and delivered to an approved disposal facility.

Wastes Disposal Location: Approved disposal facility.

Agencies Involved:

Updates

Date: 3/2/2015 Status: Reviewed; Followup Required Staff: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spray off location due to an on-location valve/piping leak. Followup is necessary.

Tuesday, March 24, 2015 Page 2 of 2